Polling Site Accessibility Report: Wood County, WV - August 2021

Disability Rights of West Virginia (DRWV) is the federally mandated protection and advocacy system for people with disabilities in West Virginia. One of DRWV's grants is Protection and Advocacy for Voting Access (PAVA). The PAVA grant program allows DRWV to ensure that individuals with disabilities can access full participation in the election process.

Title II of the Americans with Disabilities Act (ADA) requires state and local governments (public entities) to ensure that people with disabilities have a full and equal opportunity to vote. The ADA's provisions apply to all aspects of voting, including polling places. People with disabilities must have the opportunity to be full participants in an integrated civic event.

On June 2nd-4th, 2021, we completed exterior accessibility monitoring of all precincts in Wood County. The majority of the polling sites in your county are accessible or can easily be made temporarily accessible by designating accessible parking, hanging appropriate signage, and/or keeping doors opened. As such, the following ADA codes have been referenced below.

- **206.2.1** Site Arrival Points. At least one accessible route shall be provided within the site from accessible parking spaces and accessible passenger loading zones; public streets and sidewalks; and public transportation stops to the accessible building or facility entrance they serve.
- **216.6** Where not all entrances comply with 404 (Doors, Doorways, and Gates), entrances complying with 404 shall be identified by the International Symbol of Accessibility complying with 703.7.2.1. Directional signs complying with 703.5 that indicate the location of the nearest entrance complying with 404 shall be provided at entrances that do not comply with 404.
- **309.4** Operable parts shall be operable with one hand and shall not require tight grasping, pinching, or twisting of the wrist. The force required to activate operable parts shall be 5 pounds (22.2 N) maximum.
- **502.2** Vehicle Spaces. Car parking spaces shall be 96 inches (2440 mm) wide minimum and van parking spaces shall be 132 inches (3350 mm) wide minimum, shall be marked to define the width, and shall have an adjacent access aisle complying with 502.3. EXCEPTION: Van parking spaces shall be permitted to be 96 inches (2440 mm) wide minimum where the access aisle is 96 inches (2440 mm) wide minimum.
- **502.6** Identification. Parking space identification signs shall include the International Symbol of Accessibility complying with 703.7.2.1. Signs identifying van parking spaces shall contain the designation "van accessible." Signs shall be 60 inches (1525 mm) minimum above the finish floor or ground surface measured to the bottom of the sign.

The **2010 ADA Standards for Accessible Designs** referenced in this report can be found online at:

https://www.ada.gov/regs2010/2010ADAStandards/2010ADAStandards_prt.pdf

Before further review, please take time to browse the Standards to gain a better understanding of the issues addressed. The tables on the following pages list the ADA Standards and ADA Title II regulations, if applicable, for each area we monitored, the issues noted at each site, if any, and suggestions for meeting ADA compliance on election days.

Beechwood Presbyterian Church	
Issue(s)	No marked accessible parking spots. No accessible parking signage
	displayed. No handrail extensions.
2010 ADA	208.3.1 General . Parking spaces complying with 502 that serve a particular
Standards for	building or facility shall be located on the shortest accessible route from
Accessible	parking to an entrance complying with 206.4. Where parking serves more
Design	than one accessible entrance, parking spaces complying with 502 shall be
Requirements	dispersed and located on the shortest accessible route to the accessible
	entrances. In parking facilities that do not serve a particular building or
	facility, parking spaces complying with 502 shall be located on the shortest
	accessible route to an accessible pedestrian entrance of the parking facility.
	206.2.1 Site Arrival Points. At least one accessible route shall be provided
	within the site from accessible parking spaces and accessible passenger
	loading zones; public streets and sidewalks; and public transportation stops
	to the accessible building or facility entrance they serve.
	208.2 Minimum Number . Parking spaces complying with 502 shall be
	provided in accordance with Table 208.2 except as required by 208.2.1, 208.2.2, and 208.2.3. Where more than one parking facility is provided on a
	site, the number of accessible spaces provided on the site shall be
	calculated according to the number of spaces required for each parking
	facility.
	208.2.4 Van Parking Spaces. For every six or fraction of six parking spaces
	required by 208.2 to comply with 502, at least one shall be a van parking
	space complying with 502.
	403.3 An accessible route has running slope no greater than 1:20 (5%)
	502.6 Identification . Parking space identification signs shall include the
	International Symbol of Accessibility complying with 703.7.2.1. Signs
	identifying van parking spaces shall contain the designation "van
	accessible." Signs shall be 60 inches minimum above the finish floor or
	ground surface measured to the bottom of the sign.
	505.10.1 Top and Bottom Extension at Ramps. Ramp handrails shall extend
	horizontally above the landing for 12 inches (305 mm) minimum beyond the
	top and bottom of ramp runs. Extensions shall return to a wall, guard, or the

	landing surface, or shall be continuous to the handrail of an adjacent ramp
	run.
Suggestions	Add required number of marked accessible parking spots. Install accessible
for ADA	parking signage to the required height that complies with the ADA
Compliance	regulation. Install handrail extensions.

Belleville Com	munity Center
Issue(s)	No paved parking area or marked accessible parking spots. No accessible
	parking signage displayed. No entry ramp into building. Marked accessible entrance is not accessible.
2010 ADA	206.2.2 Within a Site. At least one accessible route shall connect
Standards for	accessible buildings, accessible facilities, accessible elements, and
Accessible	accessible spaces that are on the same site.
Design	206.2.1 Site Arrival Points. At least one accessible route shall be provided
Requirements	within the site from accessible parking spaces and accessible passenger
	loading zones; public streets and sidewalks; and public transportation stops
	to the accessible building or facility entrance they serve.
	208.2 Minimum Number . Parking spaces complying with 502 shall be
	provided in accordance with Table 208.2 except as required by 208.2.1, 208.2.2, and 208.2.3. Where more than one parking facility is provided on a
	site, the number of accessible spaces provided on the site shall be
	calculated according to the number of spaces required for each parking
	facility.
	208.2.4 Van Parking Spaces . For every six or fraction of six parking spaces
	required by 208.2 to comply with 502, at least one shall be a van parking
	space complying with 502.
	302.1 Floor and ground surfaces shall be stable, firm, and slip resistant and
	shall comply with 302. Access aisles shall be at the same level as the
	parking spaces they serve. Changes in level are not permitted.
	EXCEPTION: Slopes not steeper than 1:48 shall be permitted. 502.6 Identification . Parking space identification signs shall include the
	International Symbol of Accessibility complying with 703.7.2.1. Signs
	identifying van parking spaces shall contain the designation "van
	accessible." Signs shall be 60 inches minimum above the finish floor or
	ground surface measured to the bottom of the sign.
Suggestions	Pave parking area. Add required number of marked accessible parking
for ADA	spots. Install accessible parking signage to the required height that complies
Compliance	with the ADA regulation. Install a paved ramp to parking area that complies
	with ADA regulations.

Boaz Lions Club	
Issue(s)	No marked accessible parking spots or accessible parking signage
	displayed.
2010 ADA	208.2 Minimum Number . Parking spaces complying with 502 shall be
Standards for	provided in accordance with Table 208.2 except as required by 208.2.1,

Accessible Design Requirements	208.2.2, and 208.2.3. Where more than one parking facility is provided on a site, the number of accessible spaces provided on the site shall be calculated according to the number of spaces required for each parking facility.
	208.2.4 Van Parking Spaces . For every six or fraction of six parking spaces required by 208.2 to comply with 502, at least one shall be a van parking space complying with 502.
	502.6 Identification . Parking space identification signs shall include the International Symbol of Accessibility complying with 703.7.2.1. Signs identifying van parking spaces shall contain the designation "van accessible." Signs shall be 60 inches minimum above the finish floor or ground surface measured to the bottom of the sign.
Suggestions	Add required number of marked accessible parking spots. Install accessible
for ADA	parking signage to the required height that complies with the ADA
Compliance	regulation.

Blennerhassett	Blennerhassett School	
Issue(s)	Curb ramp is too steep.	
2010 ADA	403.3 An accessible route has running slope no greater than 1:20 (5%)	
Standards for		
Accessible		
Design		
Requirements		
Suggestions	Regrade curb ramp.	
for ADA		
Compliance		

Criss Elementary School	
Issue(s)	Parking lot slope is too steep. There is a curb lip to enter sidewalk.
2010 ADA	302.1 Floor and ground surfaces shall be stable, firm, and slip resistant and
Standards for	shall comply with 302. Access aisles shall be at the same level as the
Accessible	parking spaces they serve. Changes in level are not permitted.
Design	EXCEPTION: Slopes not steeper than 1:48 shall be permitted.
Requirements	Advisory 502.4 Floor or Ground Surfaces. Access aisles are required to be nearly level in all directions to provide a surface for wheelchair transfer to and from vehicles. The exception allows sufficient slope for drainage. Built-up curb ramps are not permitted to project into access aisles and parking spaces because they would create slopes greater than 1:48. 403.3 An accessible route has running slope no greater than 1:20 (5%) 303.4 Changes in level greater than ½ inch (13 mm) high shall be ramped and shall comply with 405 or 406.
Suggestions for ADA Compliance	Relocate accessible parking area and signage to flat surface area closer to entrance. Add small ramp to correct curb lip issue.

D.A.V

Issue(s)	Accessible parking signage is not displayed properly. Door hardware is not
	accessible.
2010 ADA	502.6 Identification . Parking space identification signs shall include the
Standards for	International Symbol of Accessibility complying with 703.7.2.1. Signs
Accessible	identifying van parking spaces shall contain the designation "van
Design	accessible." Signs shall be 60 inches minimum above the finish floor or
Requirements	ground surface measured to the bottom of the sign.
	404.2.7 Door hardware is operable with one hand and does not require tight
	grasping, pinching, or twisting of the wrist.
Suggestions	Remount existing signage to the required height that complies with the ADA
for ADA	regulation. Change door hardware to comply with ADA regulation.
Compliance	

Deerwalk Volui	Deerwalk Volunteer Fire Department	
Issue(s)	No marked accessible parking spots. No accessible parking signage	
	displayed.	
2010 ADA	208.2 Minimum Number . Parking spaces complying with 502 shall be	
Standards for	provided in accordance with Table 208.2 except as required by 208.2.1,	
Accessible	208.2.2, and 208.2.3. Where more than one parking facility is provided on a	
Design	site, the number of accessible spaces provided on the site shall be	
Requirements	calculated according to the number of spaces required for each parking	
	facility.	
	208.2.4 Van Parking Spaces . For every six or fraction of six parking spaces	
	required by 208.2 to comply with 502, at least one shall be a van parking	
	space complying with 502.	
	502.6 Identification . Parking space identification signs shall include the	
	International Symbol of Accessibility complying with 703.7.2.1. Signs	
	identifying van parking spaces shall contain the designation "van	
	accessible." Signs shall be 60 inches minimum above the finish floor or	
	ground surface measured to the bottom of the sign.	
Suggestions	Install accessible parking signage to the required height that complies with	
for ADA	the ADA regulation. Install required number of marked accessible parking	
Compliance	spots.	

Edison Middle	School
Issue(s)	No marked accessible parking spots. No accessible parking signage
	displayed.
2010 ADA	208.2 Minimum Number . Parking spaces complying with 502 shall be
Standards for	provided in accordance with Table 208.2 except as required by 208.2.1,
Accessible	208.2.2, and 208.2.3. Where more than one parking facility is provided on a
Design	site, the number of accessible spaces provided on the site shall be
Requirements	calculated according to the number of spaces required for each parking
	facility.
	208.2.4 Van Parking Spaces . For every six or fraction of six parking spaces
	required by 208.2 to comply with 502, at least one shall be a van parking
	space complying with 502.

	502.6 Identification . Parking space identification signs shall include the International Symbol of Accessibility complying with 703.7.2.1. Signs identifying van parking spaces shall contain the designation "van accessible." Signs shall be 60 inches minimum above the finish floor or ground surface measured to the bottom of the sign.
Suggestions for ADA Compliance	Install accessible parking signage to the required height that complies with the ADA regulation. Install required number of marked accessible parking spots.

Emerson Elementary School	
Issue(s)	Accessible parking signage is not displayed properly. Curb ramp is too
	steep.
2010 ADA	206.2.2 Within a Site. At least one accessible route shall connect
Standards for	accessible buildings, accessible facilities, accessible elements, and
Accessible	accessible spaces that are on the same site.
Design	403.3 An accessible route has running slope no greater than 1:20 (5%)
Requirements	502.6 Identification . Parking space identification signs shall include the International Symbol of Accessibility complying with 703.7.2.1. Signs identifying van parking spaces shall contain the designation "van accessible." Signs shall be 60 inches minimum above the finish floor or ground surface measured to the bottom of the sign.
Suggestions	Regrade entrance ramp. Remount existing signage to the required height
for ADA	that complies with the ADA regulation.
Compliance	

Emmanuel Baptist Church	
Issue	Entry ramp is too steep. No accessible parking signage displayed.
2010 ADA	206.2.2 Within a Site. At least one accessible route shall connect
Standards for	accessible buildings, accessible facilities, accessible elements, and
Accessible	accessible spaces that are on the same site.
Design	403.3 An accessible route has running slope no greater than 1:20 (5%)
Requirements	
Suggestions for ADA Compliance	Regrade entrance ramp. Install accessible parking signage to the required height that complies with the ADA regulation.

Fairplains Elementary School	
Issue(s)	Small curb lip to get onto sidewalk. No accessible parking signage
	displayed.
2010 ADA	302.1 Floor and ground surfaces shall be stable, firm, and slip resistant and
Standards for	shall comply with 302. Access aisles shall be at the same level as the
Accessible	

Design	parking spaces they serve. Changes in level are not permitted.
Requirements	EXCEPTION: Slopes not steeper than 1:48 shall be permitted.
	303.4 Changes in level greater than ½ inch (13 mm) high shall be ramped
	and shall comply with 405 or 406.
	502.6 Identification . Parking space identification signs shall include the
	International Symbol of Accessibility complying with 703.7.2.1. Signs
	identifying van parking spaces shall contain the designation "van
	accessible." Signs shall be 60 inches minimum above the finish floor or
	ground surface measured to the bottom of the sign.
Suggestions	Add ramp at entrance sidewalk. Install accessible parking signage to the
for ADA	required height that complies with the ADA regulation.
Compliance	

Fellowship Baptist Church	
Issue(s)	Accessible parking signage is not displayed properly.
2010 ADA	502.6 Identification . Parking space identification signs shall include the
Standards for	International Symbol of Accessibility complying with 703.7.2.1. Signs
Accessible	identifying van parking spaces shall contain the designation "van
Design	accessible." Signs shall be 60 inches minimum above the finish floor or
Requirements	ground surface measured to the bottom of the sign.
Suggestions	Remount existing signage to the required height that complies with the ADA
for ADA	regulation.
Compliance	

Gihon School	
Issue(s)	No accessible parking signage displayed.
2010 ADA	502.6 Identification . Parking space identification signs shall include the
Standards for	International Symbol of Accessibility complying with 703.7.2.1. Signs
Accessible	identifying van parking spaces shall contain the designation "van
Design	accessible." Signs shall be 60 inches minimum above the finish floor or
Requirements	ground surface measured to the bottom of the sign.
Suggestions	Install accessible parking signage to the required height that complies with
for ADA	the ADA regulation.
Compliance	

Good Shepard Church	
Issue(s)	Curb ramp is too steep. Accessible parking signage is not displayed
	properly.
2010 ADA	502.6 Identification . Parking space identification signs shall include the
Standards for	International Symbol of Accessibility complying with 703.7.2.1. Signs
Accessible	identifying van parking spaces shall contain the designation "van
Design	accessible." Signs shall be 60 inches minimum above the finish floor or
Requirements	ground surface measured to the bottom of the sign.
	206.2.2 Within a Site. At least one accessible route shall connect
	accessible buildings, accessible facilities, accessible elements, and
	accessible spaces that are on the same site.

	403.3 An accessible route has running slope no greater than 1:20 (5%)
Suggestions for ADA	Regrade ramp at entrance sidewalk. Install accessible parking signage to the required height that complies with the ADA regulation.
Compliance	

Grace Gospel (Grace Gospel Church	
Issue(s)	No marked accessible parking spots or signage.	
2010 ADA	208.2 Minimum Number . Parking spaces complying with 502 shall be	
Standards for	provided in accordance with Table 208.2 except as required by 208.2.1,	
Accessible	208.2.2, and 208.2.3. Where more than one parking facility is provided on a	
Design	site, the number of accessible spaces provided on the site shall be	
Requirements	calculated according to the number of spaces required for each parking	
	facility.	
	208.2.4 Van Parking Spaces . For every six or fraction of six parking spaces	
	required by 208.2 to comply with 502, at least one shall be a van parking	
	space complying with 502.	
	502.6 Identification . Parking space identification signs shall include the	
	International Symbol of Accessibility complying with 703.7.2.1. Signs	
	identifying van parking spaces shall contain the designation "van	
	accessible." Signs shall be 60 inches minimum above the finish floor or	
	ground surface measured to the bottom of the sign.	
Suggestions	Install accessible parking signage to the required height that complies with	
for ADA	the ADA regulation. Install required number of marked accessible parking	
Compliance	spots.	

Hamilton Middl	Hamilton Middle School	
Issue(s)	Accessible parking signage is not displayed properly. Large crack in	
	pavement along accessible walkway.	
2010 ADA	502.6 Identification . Parking space identification signs shall include the	
Standards for	International Symbol of Accessibility complying with 703.7.2.1. Signs	
Accessible	identifying van parking spaces shall contain the designation "van	
Design	accessible." Signs shall be 60 inches minimum above the finish floor or	
Requirements	ground surface measured to the bottom of the sign.	
	302.1 Floor and ground surfaces shall be stable, firm, and slip resistant and	
	shall comply with 302. Access aisles shall be at the same level as the	
	parking spaces they serve. Changes in level are not permitted.	
	EXCEPTION: Slopes not steeper than 1:48 shall be permitted.	
	303.4 Changes in level greater than ½ inch (13 mm) high shall be ramped	
	and shall comply with 405 or 406.	
Suggestions	Remount existing signage to the required height that complies with the ADA	
for ADA	regulation. Patch broken pavement or use an ADA compliant mat to cover	
Compliance	broken concrete.	

Hopewell Church of Christ

Issue(s)	No accessible parking signage. No handrail extensions. Accessible parking spots are located by drain grate with a steep slope.
	, , , , , , , , , , , , , , , , , , , ,
2010 ADA	502.6 Identification . Parking space identification signs shall include the
Standards for	International Symbol of Accessibility complying with 703.7.2.1. Signs
Accessible	identifying van parking spaces shall contain the designation "van
Design	accessible." Signs shall be 60 inches minimum above the finish floor or
Requirements	ground surface measured to the bottom of the sign.
	302.1 Floor and ground surfaces shall be stable, firm, and slip resistant and
	shall comply with 302. Access aisles shall be at the same level as the
	parking spaces they serve. Changes in level are not permitted.
	EXCEPTION: Slopes not steeper than 1:48 shall be permitted.
	403.3 An accessible route has running slope no greater than 1:20 (5%).
	505.10.1 Top and Bottom Extension at Ramps. Ramp handrails shall extend
	horizontally above the landing for 12 inches (305 mm) minimum beyond the
	top and bottom of ramp runs. Extensions shall return to a wall, guard, or the
	landing surface, or shall be continuous to the handrail of an adjacent ramp
	run.
Suggestions	Install accessible parking signage to the required height that complies with
for ADA	the ADA regulation. Cover grate and slope with ADA mat or move marked
Compliance	accessible spots away from grate and slope. Install handrail extensions.

Jefferson Elem	Jefferson Elementary School	
Issue(s)	Curb lip at curb ramp.	
2010 ADA	302.1 Floor and ground surfaces shall be stable, firm, and slip resistant and	
Standards for	shall comply with 302. Access aisles shall be at the same level as the	
Accessible	parking spaces they serve. Changes in level are not permitted.	
Design	EXCEPTION: Slopes not steeper than 1:48 shall be permitted.	
Requirements	303.4 Changes in level greater than ½ inch (13 mm) high shall be ramped	
	and shall comply with 405 or 406.	
Suggestions	Extend ramp to patch that curb lip or use an ADA compliant mat to cover lip.	
for ADA		
Compliance		

Kanawha Elementary School	
Issue(s)	No accessible parking signage.
2010 ADA	502.6 Identification . Parking space identification signs shall include the
Standards for	International Symbol of Accessibility complying with 703.7.2.1. Signs
Accessible	identifying van parking spaces shall contain the designation "van
Design	accessible." Signs shall be 60 inches minimum above the finish floor or
Requirements	ground surface measured to the bottom of the sign.
Suggestions	Install accessible parking signage to the required height that complies with
for ADA	the ADA regulation.
Compliance	

Ludeck Elementary School	
Issue(s)	No accessible parking signage displayed.

2010 ADA	502.6 Identification . Parking space identification signs shall include the
Standards for	International Symbol of Accessibility complying with 703.7.2.1. Signs
Accessible	identifying van parking spaces shall contain the designation "van
Design	accessible." Signs shall be 60 inches minimum above the finish floor or
Requirements	ground surface measured to the bottom of the sign.
Suggestions	Install accessible parking signage to the required height that complies with
for ADA	the ADA regulation.
Compliance	

Madison Elementary School	
Issue(s)	Accessible parking signage is not displayed properly.
2010 ADA	502.6 Identification . Parking space identification signs shall include the
Standards for	International Symbol of Accessibility complying with 703.7.2.1. Signs
Accessible	identifying van parking spaces shall contain the designation "van
Design	accessible." Signs shall be 60 inches minimum above the finish floor or
Requirements	ground surface measured to the bottom of the sign.
Suggestions	Remount existing signage to the required height that complies with the ADA
for ADA	regulation.
Compliance	

Mineral Wells Elementary School	
Issue(s)	No accessible parking signage displayed.
2010 ADA	502.6 Identification . Parking space identification signs shall include the
Standards for	International Symbol of Accessibility complying with 703.7.2.1. Signs
Accessible	identifying van parking spaces shall contain the designation "van
Design	accessible." Signs shall be 60 inches minimum above the finish floor or
Requirements	ground surface measured to the bottom of the sign.
Suggestions	Install accessible parking signage to the required height that complies with
for ADA	the ADA regulation.
Compliance	

MOV Regional Airport	
Issue(s)	No marked accessible parking spots. No accessible parking signage
	displayed.
2010 ADA	208.2 Minimum Number . Parking spaces complying with 502 shall be
Standards for	provided in accordance with Table 208.2 except as required by 208.2.1,
Accessible	208.2.2, and 208.2.3. Where more than one parking facility is provided on a
Design	site, the number of accessible spaces provided on the site shall be
Requirements	calculated according to the number of spaces required for each parking
	facility.
	208.2.4 Van Parking Spaces . For every six or fraction of six parking spaces
	required by 208.2 to comply with 502, at least one shall be a van parking
	space complying with 502.
	502.6 Identification . Parking space identification signs shall include the
	International Symbol of Accessibility complying with 703.7.2.1. Signs
	identifying van parking spaces shall contain the designation "van

	accessible." Signs shall be 60 inches minimum above the finish floor or ground surface measured to the bottom of the sign.
Suggestions for ADA Compliance	Install required number of marked accessible parking spots. Install accessible parking signage to the required height that complies with the ADA regulation.

New Hope Bap	New Hope Baptist Church	
Issue(s)	Inch lip to get to curb ramp. No marked accessible parking spots or signage.	
2010 ADA	302.1 Floor and ground surfaces shall be stable, firm, and slip resistant and	
Standards for	shall comply with 302. Access aisles shall be at the same level as the	
Accessible	parking spaces they serve. Changes in level are not permitted.	
Design	EXCEPTION: Slopes not steeper than 1:48 shall be permitted.	
Requirements	303.4 Changes in level greater than $\frac{1}{2}$ inch (13 mm) high shall be ramped and shall comply with 405 or 406.	
	 208.2 Minimum Number. Parking spaces complying with 502 shall be provided in accordance with Table 208.2 except as required by 208.2.1, 208.2.2, and 208.2.3. Where more than one parking facility is provided on a site, the number of accessible spaces provided on the site shall be calculated according to the number of spaces required for each parking facility. 208.2.4 Van Parking Spaces. For every six or fraction of six parking spaces required by 208.2 to comply with 502, at least one shall be a van parking space complying with 502. 502.6 Identification. Parking space identification signs shall include the 	
	International Symbol of Accessibility complying with 703.7.2.1. Signs identifying van parking spaces shall contain the designation "van	
	accessible." Signs shall be 60 inches minimum above the finish floor or	
0	ground surface measured to the bottom of the sign.	
Suggestions	Patch curb lip on entry ramp. Install required number of marked accessible	
for ADA	parking spots. Install accessible parking signage to the required height that	
Compliance	complies with the ADA regulation.	

Parkersburg High School	
Issue(s)	No accessible parking signage displayed.
2010 ADA	502.6 Identification . Parking space identification signs shall include the
Standards for	International Symbol of Accessibility complying with 703.7.2.1. Signs
Accessible	identifying van parking spaces shall contain the designation "van
Design	accessible." Signs shall be 60 inches minimum above the finish floor or
Requirements	ground surface measured to the bottom of the sign.
Suggestions	Install accessible parking signage to the required height that complies with
for ADA	the ADA regulation.
Compliance	

Parkersburg Library	
Issue(s)	No handrail extensions. Accessible parking signage is not displayed
	properly.

2010 ADA Standards for Accessible Design Requirements	502.6 Identification . Parking space identification signs shall include the International Symbol of Accessibility complying with 703.7.2.1. Signs identifying van parking spaces shall contain the designation "van accessible." Signs shall be 60 inches minimum above the finish floor or ground surface measured to the bottom of the sign. 505.10.1 Top and Bottom Extension at Ramps. Ramp handrails shall extend horizontally above the landing for 12 inches (305 mm) minimum beyond the top and bottom of ramp runs. Extensions shall return to a wall, guard, or the landing surface, or shall be continuous to the handrail of an adjacent ramp run.
Suggestions for ADA Compliance	Remount existing signage to the required height that complies with the ADA regulation. Install top and bottom handrail extensions.

Parkersburg South High School	
Issue(s)	No accessible parking signage displayed.
2010 ADA	502.6 Identification . Parking space identification signs shall include the
Standards for	International Symbol of Accessibility complying with 703.7.2.1. Signs
Accessible	identifying van parking spaces shall contain the designation "van
Design	accessible." Signs shall be 60 inches minimum above the finish floor or
Requirements	ground surface measured to the bottom of the sign.
Suggestions	Install accessible parking signage to the required height that complies with
for ADA	the ADA regulation.
Compliance	

Red Hill United Methodist Church	
Issue(s)	Accessible parking signage is not displayed properly.
2010 ADA	502.6 Identification . Parking space identification signs shall include the
Standards for	International Symbol of Accessibility complying with 703.7.2.1. Signs
Accessible	identifying van parking spaces shall contain the designation "van
Design	accessible." Signs shall be 60 inches minimum above the finish floor or
Requirements	ground surface measured to the bottom of the sign.
Suggestions	Remount existing signage to the required height that complies with the ADA
for ADA	regulation.
Compliance	

Rockport Church	
Issue(s)	Accessible parking signage not displayed properly. Door hardware is not
	accessible.
2010 ADA	502.6 Identification . Parking space identification signs shall include the
Standards for	International Symbol of Accessibility complying with 703.7.2.1. Signs
Accessible	identifying van parking spaces shall contain the designation "van
Design	accessible." Signs shall be 60 inches minimum above the finish floor or
Requirements	ground surface measured to the bottom of the sign.
	404.2.7 Door hardware is operable with one hand and does not require tight
	grasping, pinching, or twisting of the wrist.

Suggestions for ADA	Remount existing signage to the required height that complies with the ADA regulation. Change door hardware to comply with ADA regulation.
Compliance	

Rosemar United Methodist	
Issue(s)	Accessible parking signage is not displayed properly. No handrail extensions. Entry ramp in the rear of the building is too steep. Door
	hardware is not accessible.
2010 ADA	206.2.2 Within a Site. At least one accessible route shall connect
Standards for	accessible buildings, accessible facilities, accessible elements, and
Accessible	accessible spaces that are on the same site.
Design	502.6 Identification . Parking space identification signs shall include the
Requirements	International Symbol of Accessibility complying with 703.7.2.1. Signs identifying van parking spaces shall contain the designation "van accessible." Signs shall be 60 inches minimum above the finish floor or ground surface measured to the bottom of the sign. 404.2.7 Door hardware is operable with one hand and does not require tight grasping, pinching, or twisting of the wrist. 403.3 An accessible route has running slope no greater than 1:20 (5%). 505.10.1 Top and Bottom Extension at Ramps. Ramp handrails shall extend horizontally above the landing for 12 inches (305 mm) minimum beyond the top and bottom of ramp runs. Extensions shall return to a wall, guard, or the landing surface, or shall be continuous to the handrail of an adjacent ramp run.
Suggestions for ADA Compliance	Remount existing signage to the required height that complies with the ADA regulation. Change door hardware to comply with ADA regulation. Install new accessible entrance ramp at the side and rear of the building. Install handrail extensions.

Union Valley Baptist Church	
Issue(s)	No accessible parking signage.
2010 ADA	502.6 Identification . Parking space identification signs shall include the
Standards for	International Symbol of Accessibility complying with 703.7.2.1. Signs
Accessible	identifying van parking spaces shall contain the designation "van
Design	accessible." Signs shall be 60 inches minimum above the finish floor or
Requirements	ground surface measured to the bottom of the sign.
Suggestions	Install accessible parking signage to the required height that complies with
for ADA	the ADA regulation.
Compliance	

Van Devender Middle School	
Issue(s)	No accessible parking signage displayed.
2010 ADA	502.6 Identification . Parking space identification signs shall include the
Standards for	International Symbol of Accessibility complying with 703.7.2.1. Signs
Accessible	identifying van parking spaces shall contain the designation "van

Design	accessible." Signs shall be 60 inches minimum above the finish floor or
Requirements	ground surface measured to the bottom of the sign.
Suggestions	Install accessible parking signage to the required height that complies with
for ADA	the ADA regulation.
Compliance	

Washington Community Building	
Issue(s)	No accessible parking signage displayed. Sidewalk ramp is too steep.
2010 ADA	206.2.2 Within a Site. At least one accessible route shall connect
Standards for	accessible buildings, accessible facilities, accessible elements, and
Accessible	accessible spaces that are on the same site.
Design	502.6 Identification . Parking space identification signs shall include the
Requirements	
	identifying van parking spaces shall contain the designation "van
	accessible." Signs shall be 60 inches minimum above the finish floor or
	ground surface measured to the bottom of the sign.
	403.3 An accessible route has running slope no greater than 1:20 (5%).
Suggestions	Regrade entry ramp. Install accessible parking signage to the required
for ADA	height that complies with the ADA regulation.
Compliance	

Waverly Volunteer Fire Department	
Issue(s)	No marked accessible parking spots or signage displayed.
2010 ADA	502.6 Identification . Parking space identification signs shall include the
Standards for	International Symbol of Accessibility complying with 703.7.2.1. Signs
Accessible	identifying van parking spaces shall contain the designation "van
Design	accessible." Signs shall be 60 inches minimum above the finish floor or
Requirements	ground surface measured to the bottom of the sign.
Suggestions	Install accessible parking signage to the required height that complies with
for ADA	the ADA regulation.
Compliance	

Williamstown F	Williamstown Police Department	
Issue(s)	No marked accessible parking spots or signage by entrance.	
2010 ADA	208.3.1 General . Parking spaces complying with 502 that serve a particular	
Standards for	building or facility shall be located on the shortest accessible route from	
Accessible	parking to an entrance complying with 206.4. Where parking serves more	
Design	than one accessible entrance, parking spaces complying with 502 shall be	
Requirements	dispersed and located on the shortest accessible route to the accessible	
	entrances. In parking facilities that do not serve a particular building or	
	facility, parking spaces complying with 502 shall be located on the shortest	
	accessible route to an accessible pedestrian entrance of the parking facility.	
	208.2 Minimum Number . Parking spaces complying with 502 shall be	
	provided in accordance with Table 208.2 except as required by 208.2.1,	
	208.2.2, and 208.2.3. Where more than one parking facility is provided on a	
	site, the number of accessible spaces provided on the site shall be	

	calculated according to the number of spaces required for each parking facility. 208.2.4 Van Parking Spaces. For every six or fraction of six parking spaces required by 208.2 to comply with 502, at least one shall be a van parking space complying with 502. 502.6 Identification. Parking space identification signs shall include the International Symbol of Accessibility complying with 703.7.2.1. Signs identifying van parking spaces shall contain the designation "van accessible." Signs shall be 60 inches minimum above the finish floor or ground surface measured to the bottom of the sign.
Suggestions for ADA Compliance	Install accessible parking area by entrance. Install accessible parking signage to the required height that complies with the ADA regulation.

Williamstown Elementary School	
Issue(s)	Accessible parking signage is not displayed properly.
2010 ADA	502.6 Identification . Parking space identification signs shall include the
Standards for	International Symbol of Accessibility complying with 703.7.2.1. Signs
Accessible	identifying van parking spaces shall contain the designation "van
Design	accessible." Signs shall be 60 inches minimum above the finish floor or
Requirements	ground surface measured to the bottom of the sign.
Suggestions	Remount existing signage to the required height that complies with the ADA
for ADA	regulation.
Compliance	

West Virginia L	West Virginia University Parkersburg	
Issue(s)	Accessible parking signage is not displayed properly. Entry ramp is too	
	steep.	
2010 ADA	206.2.2 Within a Site. At least one accessible route shall connect	
Standards for	accessible buildings, accessible facilities, accessible elements, and	
Accessible	accessible spaces that are on the same site.	
Design	502.6 Identification . Parking space identification signs shall include the	
Requirements	International Symbol of Accessibility complying with 703.7.2.1. Signs	
	identifying van parking spaces shall contain the designation "van	
	accessible." Signs shall be 60 inches minimum above the finish floor or	
	ground surface measured to the bottom of the sign.	
	403.3 An accessible route has running slope no greater than 1:20 (5%).	
Suggestions	Regrade entry ramp. Install accessible parking signage to the required	
for ADA	height that complies with the ADA regulation.	
Compliance		

Several temporary solutions have been offered for making polling sites across Wood County accessible, and many of these solutions can easily be found online or at your local hardware store. An additional resource is West Virginia University's Center for Excellence in Disabilities WVATS (West Virginia Assistive Technology System) program. This program has portable ramps to loan for free, although pick-up and drop-

off of the ramps are required. Enclosed is a brochure with information for contacting WVATS.

The **2010 ADA Standards for Accessible Designs** referenced in this report can be found online at:

https://www.ada.gov/regs2010/2010ADAStandards/2010ADAStandards prt.pdf

Four other valuable resources have been included for your reference:

- ADA Checklist for Polling Places https://www.ada.gov/votingck.htm
- The Americans with Disabilities Act and Other Federal Laws Protecting the Rights of Voters with Disabilities https://www.ada.gov/ada_voting/ada_voting_ta.htm
- Solutions for Five Common ADA Access Problems at Polling Places https://www.ada.gov/ada-voting/voting-solutions-ta/polling-place-solutions.htm
- ADA Quick Tips Tax Incentives https://adata.org/factsheet/quicktips-tax

The ADA requires that public entities ensure that people with disabilities can access and use all voting facilities. Because a mix of public and private facilities are used as polling places, public entities may ensure Election Day accessibility of a polling place by using low-cost, temporary measures, such as portable ramps or door stops, rather than making permanent modifications to a building. If temporary measures will not fix a barrier, and public entities are unable to make a permanent modification to fix the barrier, then the public entity must look for an alternative, accessible polling place.